

Principles of welding technology

Third edition

L. M. Gourd

Formerly Group Manager, Training Services, The Welding Institute



A member of the Hodder Headline Group
LONDON • SYDNEY • AUCKLAND



Contents

Preface	v
1 Which method of joining?	1
The development of joining techniques. Manufacturing methods. Mechanically formed joints. Lap joints. Welded joints	
2 Methods of welding	8
Types of welded joint. Weld formation. Cold pressure welding. Hot pressure welding. Friction welding. Principles of fusion welding. Heat sources for fusion welding. Protection of the weld pool. Typical fusion-welding processes	
3 Essential parameters in fusion welding	38
Parent-metal fusion. Heat input. Measuring heat input in arc welding. Heat input in oxy-acetylene welding. Summary of the main factors governing heat input. Penetration and dilution in arc welding. Position of welding. Penetration and edge preparation	
4 Control of welding parameters	53
The importance of control. Control in oxy-acetylene welding. Control in arc welding. Arc-length control in TIG welding. Arc-length control in MMA welding. Self-adjusting arcs in MIG welding. Summary of heat-input control in arc welding. Supplying power for arc welding	
5 Operating characteristics of manual metal arc (MMA) welding	77
Welding current. Functions of flux covering. Functions of individual constituents of a flux. Operating characteristics of electrodes for steels. Current ranges for MMA electrodes. Choosing and specifying an electrode	
6 Operating characteristics of gas-shielded welding	88
Tungsten arc gas-shielded (TIG) welding. Metal arc gas-shielded (MIG) welding	
7 Weldability	102
Response of metals to welding. Defining weldability. Properties of a welded joint	

8 Weld quality and strength	116
Criteria for weld acceptability. Strength of butt-welded joints. Strength of fillet-welded joints. Effect of heat affected zone properties. Influence of weld defects	
9 Checking and controlling weld quality	126
Non-destructive testing. Visual inspection. Assisted visual inspection. Radiography. Ultrasonic inspection. Controlling weld quality. Approving the welding procedure. Approving the welder	
10 Shrinkage and distortion in fusion welding	146
Thermal expansion and contraction. Solidification shrinkage. Contraction of solid metal. Flame straightening. Residual stresses	
11 Mechanising arc welding	159
Factors affecting welding speed. Mechanised TIG welding. Gravity welding. Continuous-electrode systems. Consumables in submerged arc-welding. Practical welding systems. Advantages in using mechanised arc welding. Limitations of mechanised welding. Electro-slag welding. Robots for welding	
12 Resistance welding	181
Basis of resistance welding. Practical resistance-welding systems. Quality control in resistance welding. Flash welding	
13 Welding with power beams	197
Keyholing. Plasma-arc systems. Electron-beam welding. Laser systems	
14 Thermal cutting systems	208
Oxygen cutting. Oxygen-arc cutting. Air-arc cutting and gouging. Plasma-arc cutting. Laser cutting	
15 Which process?	220
The range of factors influencing choice. Technical considerations. Costs of the welding operation. Conclusions	
Appendix: safety in fusion welding	228
Safety in arc welding. Electrical hazards. Radiation from the arc. Production of fume. Gaseous contaminants. Safety in oxy-acetylene welding	
Index	240

Index

A.C

- rectification 69-70, 91
- welding 66-68, 77-78, 89
- acetylene 14, 26-27, 41-42, 53-54, 237-239
- adhesive bonding 6
- air-arc cutting 217
- alloying elements in steel 109
- aluminium alloys 113
- arc
 - blow 77
 - characteristics 55-56
 - column 43
 - heat distribution 43-44, 89, 151-153
 - heat input 40-41, 110, 151
 - initiation 78, 90
 - length 44
 - control 56-64
 - plasma 199-200
 - stability 57, 77, 93
- atomic contact (pressure welding) 11
- austenitic stainless steel 114
- axes of rotation (robots) 174

Backing

- flux 169
 - gas 88
 - permanent 50, 169
- basic fluxes 84, 87
- bolting 2, 5
- bonding 6, 7, 11, 16
- boundary layer 210-211
- burn-back (backfire) 214
- burn-off rate 60-63

Carbon equivalent 109-112

- cartesian-coordinate robot 174
- cellulosic fluxes 84, 87
- centre-line cracking 115
- Charpy test 123-124
- classification
 - electrodes 86-87
 - steels 104
- CO₂ laser 205
- CO₂ welding, *see* MIG welding
- cold pressure welding 11-12
- combustion 41-42, 209

- constant-potential outputs 61-62, 70
- consumable-guide welding 172-173
- continuous-electrode systems 162-164
- contraction 147-150
- controlled-arc 163
- control systems for robots 178
- cooling rate 107-111, 112
- cost of welding 222-226
- cored electrode 94, 164
 - self-shielded, 95
- crack detection 128-130, 138
- cracking 102, 103, 107-112
- crater 147
- CTOD test 125
- cutting
 - arc 215-218
 - laser 218
 - oxygen-fuel gas 208-214
 - plasma 218

D.C. component 90

- defects 38, 103, 116, 120, 126
- degrees of freedom (robots) 175
- dendrites 21
- deoxidation 81, 94
- deposition rate (efficiency) 85
- design throat 117-119
- dilution 43-45
- dip transfer 99, 100
- distortion 150-153, 168, 173, 202
 - longitudinal 152
 - transverse 152-153
- drooping characteristic 58
- duplex steels 114
- duty cycle 223
- dye penetrant inspection 128, 138

Earth connection 230

- edge preparation 48-51, 152, 167
- electrical hazards 229-231
- electric-arc welding, *see* MMA welding
- electrode
 - acid 83
 - basic 84
 - cellulosic 84
 - classification 86-87
 - cored 94, 95, 164

- coverings 83-85
- current ranges 86
- efficiency 85
- iron powder 85
- non-consumable 88
- polarity 77, 89, 98
- rutile 84
- tungsten 89
- electro-gas welding 169
- electron
 - emission 200-201
 - gun 200
- electron beam welding 200-204
- electro-slag welding 169-173

- Filters 231, 237
- flame
 - straightening 154
 - neutral 53
 - temperature 23, 42
- flash welding 195-196
- flat characteristic 62
- flux
 - cored electrode 94-95, 164
 - constituents 83
 - function 79-83
 - shielding 25, 79, 165
- forge welding 13
- friction welding 15-19
- fume
 - extraction 234-235
 - hazards 232-235
- fusion 7, 20
 - boundary 20, 21
 - lack of 38

- Gamma rays 130
- gas
 - generation (ozone etc) 235
 - shielding 25, 92, 93, 95-98
- gas-shielded metal arc welding,
 - see MIG welding
- gas-shielded tungsten arc welding,
 - see TIG welding
- grain growth 20-21
- gravity welding 160-162

- Hardenable steels 105-106, 107-111, 202, 213
- heat
 - flow 20-21, 105-106, 146
 - input 20-21, 39-43, 110-112, 155, 159
 - sources 22-25
- heat affected zone 105-111, 213
- high-frequency induction welding 14-15
- high frequency spark generation 90-91
- hot pressure welding 13-15
- hydrogen in weld pool 25, 82, 110-112

- Ignitron 185
- impact strength (Charpy value) 87, 123-124
- inductance 67, 68, 98
- inverter systems
 - arc welding power supplies 75-76
 - operation 74
- iron-powder electrodes 85
- isotopes 133

- Joint
 - edge preparation 48-51, 152, 167
 - type 4, 8-10
- jointed arm robot 175

- Key-hole techniques 197-199

- Lack of fusion 38
- lap joint 4-6, 8, 9
- laser cutting 218
- laser systems 203-205
- laser welding 205-207
- leg length 47, 118, 127

- Magnetic-particle inspection 129-130
- MIG/MAG welding 32-33, 93-101, 162, 165, 176, 177
- mains variations 70
- manual metal arc welding,
 - see MMA welding
- martensitic stainless steel 114
- mechanical properties 87, 119
- mechanical tests 123-125, 142-143
- mechanised arc welding 34-35, 160-168
- metal active gas (MAG) welding,
 - see MIG/MAG welding
- metal arc gas shielded welding,
 - see MIG/MAG welding
- metal inert gas (MIG) welding,
 - see MIG/MAG welding
- metal transfer
 - dip 99-100
 - frequency 99-100
 - pulse 98, 101
 - short circuit 98-100
 - spray 98-99
- MMA welding 30-31, 60, 77-87
- motor generator 65
- multi-operator units 68

- Narrow gap welding 167
- neutral flame 53
- nitrogen absorption 25, 44
- non-destructive testing 128-138
- notch brittleness and ductility 122-125
 - in electroslag welds 173
- Overheads 224
- oxy-acetylene welding 26-27
 - flame 23, 41-42, 53-54
 - torch 55
- oxygen-arc cutting 215-217
- oxygen-fuel gas cutting 208-215
- oxygen-laser cutting 218-219
- oxygen in weld pool 24-25, 44, 79-82
- Penetration 43-45
- phase shift 184-186
- pinch force (effect) 98-99
- plasma
 - in arc 199-200
 - cutting 218
 - welding 200
- polar-coordinate robots 174
- polarity 77, 89, 98
- porosity 25, 103
- positions of welding 45-48
- power-supply characteristics 57-63
- power-supply units 64-76
 - operating problems 70
 - remote control 70
 - ripple 69
- precipitation-hardening alloys 106-107, 113
- pre-heat 40, 111, 211
- pressure welding 11-15
- procedure approval 140-145
- process selection 220-222
- projection welding 192-193
- properties of welded joint 105
- pulsed current 93, 98-101
- Quality control
 - principles 137, 139-140
 - resistance welding 193-195
 - standards 140
- Radial friction welding 18
- radiation from arc 43, 89, 231-232
- radiography 130-134
- reactor 67-68, 70
- recrystallisation 106
- rectification 69-70, 91-92
- regulators, gas 53-54
- residual stresses 155-156
- resistance
 - contact 181-182
 - heating 24, 98, 169, 181-183
 - projection welding 192-193
 - seam welding 190
 - series welding 189
 - slag bath 169
 - spot welding 36-7, 188-190
- robots for welding 173-180
- rocker-arm welder 188
- roller-spot welding 190
- root insert 88
- Safety
 - arc welding 228-237
 - oxy-acetylene welding 237-239
 - radiography 133-134
- saturable reactor 68
- seam tracking (robots) 176-178
- self-adjusting arc 60-63
- self-shielded electrode 95
- series welding 189
- shielding gas
 - classification 97-98
 - MIG/MAG 95
 - plasma arc 199, 218
 - TIG 92
- short circuit 98
- shrinkage 146-147
- shunting 187
- silicon 83, 94
- slag 25, 80-81
- soldering 5-6
- solidification
 - cracking 45, 112
 - mechanism 19-21
 - shrinkage 146-147
- solid-phase welding,
see pressure welding
- solid-state power units 71-76
- spark starter 90
- spot welding 5, 36-37, 188-190
- stainless steel 114
- static characteristics,
see power supply characteristics
- stick electrode welding,
see MMA welding
- stitch welding 190
- storage of gases 238
- strength of welded joints 117-119
- stress concentrations 120
- stress-relieving 156-158
- strip electrode 166
- submerged arc welding 34-35, 162-167
- surface tension 80
- surfacing 160

- TIG welding 28-29, 56-60, 88-93,
159-161, 176
- testing
- destructive 122-125, 142-143, 194
 - dye-penetrant 128, 138
 - magnetic particle 129, 138
 - radiography 130-134, 138
 - ultrasonic 134-137, 138
- thermal conductivity 39
- thermal expansion 146
- thoriated electrode 89-90
- three-phase power supply units 64-66,
69, 187
- threshold deformation 11, 12
- throat thickness 117-118, 127
- thyristor controls
- arc welding 71-72
 - resistance welding 185
- transformer 66-67, 184, 185
- transistorised power supply units 72-73
- tubular electrode 164
- tungsten arc gas shielded welding,
see TIG welding
- Ultrasonic flaw detection 134-137, 138
- Vacuum chamber 200, 202
- vertical welding 46-47, 80, 98, 169-173
- visual inspection 126-130
- Weaving 47
- weld
- definition 11
 - formation 11
 - metal 111-115
 - nugget 184
 - pool 20-22
- weldability 103-105
- welder approval 145
- welding
- costs 222-226
 - current 77, 89, 98, 183
 - position 45-48
 - procedure 140-145
 - speed 41, 160
- workhardening 105-106
- X-rays 130-134
- YAG laser 204-205
- Zirconiated electrode 89-90